



After the software update to version 158 (or higher), these functions are available.

Assumed that the touch handsets have the following software versions:

- Gigaset SL930H: software version 24
- Gigaset SL910H: software version 84
- Gigaset S820H: software version 41

After update/downgrade please check the settings of the base station.

If a handset doesn't work correctly after update/downgrade, please register this handset again.

Function	SL930H	SL910H	S820H	Note
Registering / Operation	OK	OK	OK	
Outgoing call	OK	OK	OK	
Incoming call	OK	OK	OK	
Call waiting	OK	only visual	only visual	
CLIP indication on handset	OK	OK	OK	
Caller ID / Caller name	OK	OK	OK	
Display Picture CLIP	-	OK	OK	SL930H: It is only an image section displayed
Caller list	OK	OK	OK	
MWI (Message waiting indicator)	OK	OK	OK	
Call transfer to internal user	OK	OK	OK	
Internal calls	OK	OK	OK	
Playing back messages from the answering machine	OK	OK	OK	SL910H, S820H: only one answering machine assignable; SL930H: all three answering machines assignable
Listen in to incoming messages	-	OK	-	
Picking up a call from the answering machine	OK	OK	OK	
Configuration of the base station	-	-	-	Possible with restrictions, it will not support all functions
Repeater (old /2.0)	OK	OK	OK	
SMS	-	OK	OK	SL930H does not support SMS
Phonebook transfer	OK	OK	OK	
Take over date and time from base	OK	OK	OK	
ECO-DECT + (ECO Mode Plus)	OK	OK	OK	
ECO-DECT display symbol: Display of a symbol for reduced DECT intensity	OK	OK	OK	