

English version (Die [deutsche Version](#) finden Sie unten)

Firmware update (version 241) 03/2017

Products:

Gigaset A510IP, C430IP, C430A IP, C530IP, C530A IP, C590IP, C595IP, C610IP, C610A IP, N300IP, N300A IP

Gigaset C430A GO, C530A GO, CL750A GO, E630A GO, S850A GO, SL400A GO, SL450A GO

Improvements and changes with firmware update:

- Information about registered handsets in WEB configurator (status pages) visible
- Operating time of device in WEB configurator visible
- Answering machines: remaining recording time, recording quality and activation status visible in WEB configurator
- Help texts in Turkish language available
- Support of Turkish characters
- Firmware update* for Gigaset HX handsets
- SIP UPDATE can be set in WEB configurator
- Improvements and bug fixes

*Information regarding firmware update for Gigaset HX handsets

With new firmware 241 it is possible to carry out a firmware update for Gigaset HX handsets.

Please reregister your Gigaset HX handsets after you updated your Gigaset IP or GO product with firmware version 241.

Deutsche Version

Firmware Update (Version 241) 03/2017

Produkte:

Gigaset A510IP, C430IP, C430A IP, C530IP, C530A IP, C590IP, C595IP, C610IP, C610A IP, N300IP, N300A IP

Gigaset C430A GO, C530A GO, CL750A GO, E630A GO, S850A GO, SL400A GO, SL450A GO

Verbesserungen und Änderungen mit dem Firmware Update:

- Information über registrierte Mobilteile; im WEB Konfigurator (Statusseiten) sichtbar
- Betriebsdaueranzeige des Gerätes im WEB Konfigurator (Statusseiten) sichtbar
- Anrufbeantworter: verbleibende Aufzeichnungszeit, Aufzeichnungsqualität und Aktivierung im WEB Konfigurator (Statusseiten) sichtbar
- Hilfetexte in türkischer Sprache verfügbar
- Unterstützung des türkischen Zeichensatzes bei der Texteingabe
- Firmware-Aktualisierung* für Gigaset HX Mobilteile
- SIP UPDATE schaltbar im WEB Konfigurator
- Verbesserungen und Fehlerbehebung

*Hinweis zum Firmware update für HX Mobilteile

Mit der neuen Firmware-Version 241, für Ihre Gigaset IP und GO Produkte, können nun auch Ihre Gigaset HX-Mobilteile eine Firmware-Aktualisierung durchführen.

Bitte melden Sie Ihre Gigaset HX-Mobilteile erneut an, nachdem Sie die Firmware-Aktualisierung, auf die Version 241, vorgenommen haben.